取出ロボットオプション ROBOT OPTION

スマートハンドアダプタ Smart Hand Adapter (SHA)

Applicable Robots

HRXII-100~1000 i/b シリーズ


HRXII-100~1000 i/b Series



10kg 可搬ポート無し 10kg Smart Hand Adapter without ports (SHA-10)



10kg 可搬ポート有り 10kg Smart Hand Adapter with ports (SHA-10)



35kg 可搬ポート有り 35kg Smart Hand Adapter with ports (SHA-35)

多品種小中量生産でのチャック板交換を時間短縮したい方へ

To reduce EOAT change time in the factories which are handling with small and medium quantities of a large variety of goods.

チャック板交換における悩み

- ●配線、配管、取付ボルト(4本)全てをやり直しのため、時間 がかかる(最低10分)。
- ②位置決めがあいまいなので、チャックトライの時に再度位置 合わせを教示する必要がある。
- ③チャック板を間違えて取り付ける事がある。
- 4配線や配管の位置を間違える事がある。



スマートハンドアダプタ仕様により上記の悩みが解決できます。

- ロフンタッチで取り付け可能で、電気ポート、エアポート付で 配線配管不要。時間15秒
- ②位置決めピンがあるので、チャックトライ時の再現性が高い。
- 3自動チャック交換ならチャック板が違うとエラーが出て、間 違える事がない。
- ◆電気ポート、エアポートがあるので、配線、配管を間違える 事がない。

The problems in regards to change the EOAT.

- 1 It takes time to do all installation again such as the sensor wiring, tubing and mounting four pieces of screws (10 minutes at least).
- 2 Re-teaching of positioning is needed after EOAT change because the position is not perfect.
- 3 Wrong EOAT might be installed.
- 4 Wrong installation of wiring or tubing happens.



Smart Hand Adapter can solve these problems as the above.

- **1** EOAT with guick changer without wiring and tubing (10
- 2 High repeatability with positioning pin of Smart Hand
- 3 No mistakes with EOAT automatic change. When different EOAT is installed on the attachment plate, the robot recognizes it as an error.
- 4 No mistakes of wiring and tubing because Smart Hand Adapter has ports on it.

自動チャック交換実例 Example of EOAT automatic change

自動チャック交換にすれば、さらに簡単にチャック板交換が 可能になります。(応相談)

With EOAT automatic change, EOAT change is much easier (On request).









着脱簡単!確実交換!

エア、電気も一発着脱!(ポート有り)

Easy and reliable change.

Installing tubing and wiring at the moment (with ports).






注 意 IMPORTANT


製品選定・使用に際し、可搬重量および重心距離を下記 のグラフにてご確認ください。

Please check the payload and distance between center of the adapter and center of gravity of EOAT in the following graph when selecting and using the adapter.

SHA シリーズ許容ねじれ荷重 A load when Ry operation



SHA シリーズ許容曲げ荷重 A load when Rx operation



R-51 R-52